

Inspection Photos
Location Name: Wildhorse 04-0424H
Location ID: 427197



Photo 1 – Pumping Unit



Photo 2 – Wellhead Sign

Inspection Photos
Location Name: Wildhorse 04-0424H
Location ID: 427197



Photo 3 – Tank Battery



Photo 4 – Heater Treaters

Inspection Photos
Location Name: Wildhorse 04-0424H
Location ID: 427197



Photo 5 – ECD and Flare