



39.91882, -108.3637, 6740.5ft, 22°
03/02/2021 02:36:43 PM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 1. Location.

RGU 23-35-198 pad
Inspection: 700405615



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 2. Wells.

RGU 23-35-198 pad
Inspection: 700405615



39.91926, -108.36264, 6734.7ft, 342°
03/02/2021 02:51:08 PM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 3. Well RGU 332-35-198 without a well sign.

**RGU 23-35-198 pad
Inspection: 700405615**



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 4. Building.

RGU 23-35-198 pad
Inspection: 700405615



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 5. Separators.

RGU 23-35-198 pad
Inspection: 700405615



39.91953, -108.36369, 6723.7ft, 350°
03/02/2021 02:41:14 PM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 7. Pig station.

RGU 23-35-198 pad
Inspection: 700405615