

Inspection Photos
Location Name: Allen 44-8 #1
Location ID: 313364



Photo 1. Photo of combustor with flames. Photo taken from entrance to location.



Photo 2. Emergency services on location.