

**Inspection Photos**  
**Location Name: Maudlin Gulch Unit 22R M-22R**  
**Location ID: 391812**



**Photo 1. Overview of location taken at entrance facing southwest.**



**Photo 2. No bradenhead access apparent.**