

Inspection Photos
Location Name: Maudlin Gulch Unit 4
Location ID: 312846



Photo 1. Overview of location taken at entrance facing northwest.



Photo 2. No bradenhead access apparent.

