

Inspection Photos
Location Name: Hiawatha State 2-36
Location ID: 313297



Photo 1. Overview of location taken at entrance facing east.



Photo 2. No bradenhead access apparent.

Inspection Photos
Location Name: Hiawatha State 2-36
Location ID: 313297



Photo 3. Stained soil on location.



Photo 4. Bucket with oily rags at wellhead.