

Inspection Photos
Location Name:
North Platte P-T-34HZ Pad
Location ID: 429920



Photo #1 Location



Photo #2 Tank Battery

Inspection Photos
Location Name:
North Platte P-T-34HZ Pad
Location ID: 429920



Photo #3 ECDs



Photo #4 Well

Inspection Photos
Location Name:
North Platte P-T-34HZ Pad
Location ID: 429920




Photo #5 Not LO/TO or Marked



Photo #6 Not Marked

Inspection Photos
Location Name:
North Platte P-T-34HZ Pad
Location ID: 429920



Photo #7 Not LO/TO



Photo #8 Stained soil/ Oily skid

Inspection Photos
Location Name:
North Platte P-T-34HZ Pad
Location ID: 429920




Photo #9 Stained soil/ Oily skid



Photo #10 Stained soil/ Oily skid

Inspection Photos
Location Name:
North Platte P-T-34HZ Pad
Location ID: 429920



Photo #11 Stained soil/ Oily skid



Photo #12 Stained soil/ Oily skid

Inspection Photos
Location Name:
North Platte P-T-34HZ Pad
Location ID: 429920




Photo #13 Stained soil



Photo #14 Stained Soil

Inspection Photos
Location Name:
North Platte P-T-34HZ Pad
Location ID: 429920



Photo #15 Unused Equipment



Photo #16 Unused Equipment

Inspection Photos
Location Name:
North Platte P-T-34HZ Pad
Location ID: 429920



Photo #17 Weathered Berm



Photo #18 Weathered Berm

Inspection Photos
Location Name:
North Platte P-T-34HZ Pad
Location ID: 429920



Photo #19 Weathered Berm



Photo #20 Weathered Berm

Inspection Photos
Location Name:
North Platte P-T-34HZ Pad
Location ID: 429920



Photo #21 Unused Equipment



Photo #22 Unused Equipment

Inspection Photos
Location Name:
North Platte P-T-34HZ Pad
Location ID: 429920



Photo #23 Stained soil



Photo #24 Stained Soil

Inspection Photos
Location Name:
North Platte P-T-34HZ Pad
Location ID: 429920



Photo #25 Stained soil/ well



Photo #26 Stained well

Inspection Photos
Location Name:
North Platte P-T-34HZ Pad
Location ID: 429920



Photo #27 Weathered Placards



Photo #28 Weathered Placards