

Inspection Photos
Location Name:
North Platte 32-34
Location ID: 413457



Photo #1 Tank Battery/ ECD's

Photo #2 Production Equipment.

Inspection Photos
Location Name:
North Platte 32-34
Location ID: 413457



Photo #3 Unmarked riser

Photo #4 Unmarked riser

Inspection Photos
Location Name:
North Platte 32-34
Location ID: 413457



Photo #5 Trash



Photo #6 Trash

Inspection Photos
Location Name:
North Platte 32-34
Location ID: 413457



Photo #7 Unused Equipment “stainless line”

Photo #8 Weathered berm

Inspection Photos
Location Name:
North Platte 32-34
Location ID: 413457



Photo #9 Weathered berm

Photo #10 Weathered Berm

Inspection Photos
Location Name:
North Platte 32-34
Location ID: 413457



Photo #11 Unmarked riser




Photo #12 Unmarked riser

Inspection Photos
Location Name:
North Platte 32-34
Location ID: 413457



Photo #13 Unmarked riser and not LO/TO. Unused stainless line

Photo #14 Unmarked riser

Inspection Photos
Location Name:
North Platte 32-34
Location ID: 413457



Photo #15 Stained soil

Photo #16 Stained soil

Inspection Photos
Location Name:
North Platte 32-34
Location ID: 413457



Photo #17 Stained soil



Photo #18 Not LO/TO or marked risers.

Inspection Photos
Location Name:
North Platte 32-34
Location ID: 413457



Photo #19 Unmarked Risers

Photo #20 Trash

Inspection Photos
Location Name:
North Platte 32-34
Location ID: 413457



Photo #21 Unused Equipment

Photo #22 Unused Equipment

Inspection Photos
Location Name:
North Platte 32-34
Location ID: 413457



Photo #23 Trash

Photo #24 Trash

Inspection Photos
Location Name:
North Platte 32-34
Location ID: 413457



Photo #25 Unused Equipment

Photo #26 Unused Equipment