

Inspection Photos
Location Name: North Platte 41-34 Pad
Location ID: 413974



Photo #1 Wells



Photo #2 Well

Inspection Photos
Location Name: North Platte 41-34 Pad
Location ID: 413974



Photo #3 Stained soil/ Mechanical conditions



Photo #4 Weathered Placard

Inspection Photos
Location Name: North Platte 41-34 Pad
Location ID: 413974



Photo #5 Unused Equipment



Photo #6 Unused Equipment

