

Inspection Photos
Location Name: Wildhorse 05-0514H
Location ID: 427525



Photo 1 – Pumping Unit



Photo 2 – Tank Battery Sign

Inspection Photos
Location Name: Wildhorse 05-0514H
Location ID: 427525




Photo 3 – Stained Soil at Wellhead



Photo 4 – Stained Soil at Exhaust



Inspection Photos
Location Name: Wildhorse 05-0514H
Location ID: 427525



Photo 5 – Tank Battery



Photo 6 – Heater Treater

Inspection Photos
Location Name: Wildhorse 05-0514H
Location ID: 427525



Photo 7 – Flare and ECD



Photo 8 – Heater Treater