

## Inspection Photos

Location Name: CAERUS PICEANCE LLC Hagen Federal /22-8A (PC22)

Location ID: 432551



Photo #3045 from entrance to location.



Photo #3046 Rutting present on location due to lack of stabilization.

## Inspection Photos

Location Name: CAERUS PICEANCE LLC Hagen Federal /22-8A (PC22)

Location ID: 432551



**Photo #3047** Rutting present on location due to lack of stabilization.



**Photo #3048** Rutting present on location due to lack of stabilization.

## Inspection Photos

Location Name: CAERUS PICEANCE LLC Hagen Federal /22-8A (PC22)

Location ID: 432551



**Photo #3049 No form of tracking control at entrance to location.**