

# Inspection Photos

Operator: Fritz & Digman  
API: 067-06141  
Date: 3/3/2021




Photo 1. View of the project area from the southwestern corner facing center. Russian knapweeds appear to be treated, but need to be assessed during the active growing season.





Photo 2. View of the southern project area from the southeastern corner facing northward. Vegetation is largely comprised of sagebrush, which is largely continuous with the surrounding sagebrush shrubland.





Photos 3/4. View of rutting and tracking up to 15 inches deep and wide observed along the access road.





Photo 5. View of the reference area comprised of sagebrush shrubland with understory of grasses and forbs such as James galleta and forbs in a dormant condition at this time.