

**Inspection Photos**  
**Operator: Red Mesa**  
**API: 067-06542**  
**Date: 3/3/2021**



Photo 1. View of the wellhead and surrounding equipment/risers.



Photo 2. View of pit area approximately 8 feet long and wide, within the southern project area.



Photos 3. View of dormant Russian knapweeds (adjacent to boot) along the access road.