

**Inspection Photos**  
**Location Name:**  
**70 Ranch 4-63-3 Pad**  
**Location ID: 434077**



**Photo #1 Location**



**Photo #2 Tank Battery**

**Inspection Photos**  
**Location Name:**  
**70 Ranch 4-63-3 Pad**  
**Location ID: 434077**



**Photo #3 Unused Equipment**



**Photo #4 Trash**



**Inspection Photos**  
**Location Name:**  
**70 Ranch 4-63-3 Pad**  
**Location ID: 434077**




**Photo #5 Unused Equipment**



**Photo #6 Unused Equipment**



**Inspection Photos**  
**Location Name:**  
**70 Ranch 4-63-3 Pad**  
**Location ID: 434077**




**Photo #7 Stained Soil/ Mechanical Conditions**



**Photo #8 Stained Soil/ Mechanical Conditions**



**Inspection Photos**  
**Location Name:**  
**70 Ranch 4-63-3 Pad**  
**Location ID: 434077**





**Photo #9 Stained Soil/ Mechanical Conditions**



**Photo #10 Stained Soil/ Mechanical Conditions**



**Inspection Photos**  
**Location Name:**  
**70 Ranch 4-63-3 Pad**  
**Location ID: 434077**



**Photo #11 Stained Soil/ Mechanical Conditions**

**Photo #12 Stained Soil/ Mechanical Conditions**



**Inspection Photos**  
**Location Name:**  
**70 Ranch 4-63-3 Pad**  
**Location ID: 434077**



**Photo #13 Trash**



**Photo #14 Trash**



**Inspection Photos**  
**Location Name:**  
**70 Ranch 4-63-3 Pad**  
**Location ID: 434077**



**Photo #15 Spill**



**Photo #16 Spill**



**Inspection Photos**  
**Location Name:**  
**70 Ranch 4-63-3 Pad**  
**Location ID: 434077**



**Photo #17 Spill**



**Photo #18 Spill**



**Inspection Photos**  
**Location Name:**  
**70 Ranch 4-63-3 Pad**  
**Location ID: 434077**



**Photo #19 Spill**



**Photo #20 Stained Soil**



**Inspection Photos**  
**Location Name:**  
**70 Ranch 4-63-3 Pad**  
**Location ID: 434077**



**Photo #21 Stained Soil**



**Photo #22 Stained Soil**



**Inspection Photos**  
**Location Name:**  
**70 Ranch 4-63-3 Pad**  
**Location ID: 434077**



**Photo #23 Unmarked or LO/TO Riser**



**Photo #24 Unmarked or LO/TO Riser**



**Inspection Photos**  
**Location Name:**  
**70 Ranch 4-63-3 Pad**  
**Location ID: 434077**




**Photo #25 Stained Soil**




**Photo #26 Oily Waste**



Inspection Photos  
Location Name:  
70 Ranch 4-63-3 Pad  
Location ID: 434077




**Photo #27 Unmarked or LO/TO Riser**



**Photo #28 Trash**



**Inspection Photos**  
**Location Name:**  
**70 Ranch 4-63-3 Pad**  
**Location ID: 434077**



**Photo #29 Stained Soil**



**Photo #30 Stained Soil/ Oily Waste in Bucket**



**Inspection Photos**  
**Location Name:**  
**70 Ranch 4-63-3 Pad**  
**Location ID: 434077**



**Photo #31 Stained Soil**



**Photo #32 Stained Soil/ Mechanical Conditions**



**Inspection Photos**  
**Location Name:**  
**70 Ranch 4-63-3 Pad**  
**Location ID: 434077**



**Photo #33 Stained Soil/ Mechanical Conditions**



**Photo #34 Stained Soil/ Mechanical Conditions**



**Inspection Photos**  
**Location Name:**  
**70 Ranch 4-63-3 Pad**  
**Location ID: 434077**



**Photo #35 Stained Soil/ Mechanical Conditions**



**Photo #36 Stained Soil/ Mechanical Conditions**



**Inspection Photos**  
**Location Name:**  
**70 Ranch 4-63-3 Pad**  
**Location ID: 434077**



**Photo #37 Trash**



**Photo #38 Trash**



**Inspection Photos**  
**Location Name:**  
**70 Ranch 4-63-3 Pad**  
**Location ID: 434077**



**Photo #39 Oily Waste**



**Photo #40 Stained Soil**