



PHOTO: VIEW OF POSITIVELY LOCATED AS-DRILLED WELL CASING CAMERA ANGLE: NORTHERLY



PHOTO: VIEW OF POSITIVELY LOCATED AS-DRILLED WELL CASING CAMERA ANGLE: EASTERLY

## GREAT WESTERN OPERATING COMPANY

GUTSHALL #1  
NE 1/4 NW 1/4, SECTION 31, T1S, R66W, 6th P.M.  
ADAMS COUNTY, COLORADO



UELS, LLC  
Corporate Office \* 85 South 200 East  
Vernal, UT 84078 \* (435) 789-1017

TAKEN BY	M.M., G.W.	02-03-21	
DRAWN BY	C.C.	02-04-21	
LOCATION PHOTOS			PHOTO 1





**PHOTO: VIEW OF POSITIVELY LOCATED AS-DRILLED WELL CASING    CAMERA ANGLE: SOUTHERLY**



**PHOTO: VIEW OF POSITIVELY LOCATED AS-DRILLED WELL CASING    CAMERA ANGLE: WESTERLY**

## **GREAT WESTERN OPERATING COMPANY**

**GUTSHALL #1  
NE 1/4 NW 1/4, SECTION 31, T1S, R66W, 6th P.M.  
ADAMS COUNTY, COLORADO**



**UELS, LLC**  
Corporate Office \* 85 South 200 East  
Vernal, UT 84078 \* (435) 789-1017

TAKEN BY	M.M., G.W.	02-03-21	
DRAWN BY	C.C.	02-04-21	
<b>LOCATION PHOTOS</b>			<b>PHOTO 2</b>





**PHOTO: VIEW OF POSITIVELY LOCATED AS-DRILLED WELL CASING**

**CAMERA ANGLE: ABOVE**

**GREAT WESTERN OPERATING COMPANY**

**GUTSHALL #1  
NE 1/4 NW 1/4, SECTION 31, T1S, R66W, 6th P.M.  
ADAMS COUNTY, COLORADO**



**UELS, LLC**  
Corporate Office \* 85 South 200 East  
Vernal, UT 84078 \* (435) 789-1017

TAKEN BY	M.M., G.W.	02-03-21	
DRAWN BY	C.C.	02-04-21	
<b>LOCATION PHOTOS</b>			<b>PHOTO 3</b>