

Inspection Photos

Loc#334921

Operator: Caerus

Insp#: 692403128

Insp Date: 3/4/21



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:
Overview of Location from entry.

March 4, 2021



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Caerus HMU Loc#334893



Photo#2:
Interim areas




March 4, 2021



Photo#3:
Access road.

March 4, 2021



Photo#4:
Access road.

Caerus HMU Loc#334893