

Inspection Photos

Loc#334952

Operator: Caerus

Insp#: 692403131

Insp Date: 3/4/21



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:
Overview of Location from entry.

March 4, 2021



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Caerus HMU Loc#334924



Photo#2:
Interim area.

March 4, 2021



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Caerus HMU Loc#334924



Photo#3:
Rutting on Pad.

March 4, 2021



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#4:
Rutting/ponding on Pad.

Caerus HMU Loc#334924