

# *Inspection Photos*

*Loc#334952*

*Operator: Caerus*

*Insp#: 692403126*

*Insp Date: 3/4/21*





Photo#1:  
Overview of Location from entry.

March 4, 2021



Photo#2:  
Overview of Location to Southwest.

March 4, 2021



Photo#3:  
Interim area.

March 4, 2021



Photo#4:  
Interim area.

Caerus Benzel Loc#334919