

Final Reclamation Inspection

February 26, 2021

Operator: DIVERSIFIED OPERATING CORPORATION - #24461

Location ID: 408218

Inspection Document #: 697502622

Weld County, CO

SESW Section 16 T8N R58W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: SOONER UNIT #14-16
Location ID: 408218



Photo 1. Photo taken from the well location entrance, facing South. Photo illustrates the Operator has performed final reclamation activities along a portion of a flowline that went to the southern facility location.

Inspection Photos
Location Name: SOONER UNIT #14-16
Location ID: 408218



Photo 2. Photo taken from the well location entrance, facing North. See comments under Photo 1.

Inspection Photos
Location Name: SOONER UNIT #14-16
Location ID: 408218



Photo 3. Photo taken from the well location, facing Northeast. See comments under Photo 1.

Inspection Photos
Location Name: SOONER UNIT #14-16
Location ID: 408218



Photo 4. Photo taken from a section of flowline associated with 123-13452, facing West. Remediation Project #8549 is still active and open; hence, the monitoring wells shown in the photo.