

Caerus Piceance LLC  
B33NE  
Location # 335370

Mar 8, 2021 at 11:31:59 AM  
39.490146,-107.667348 ±37.21m  
COGCC



location

Mar 8, 2021 at 11:33:29 AM  
39.490180,-107.667463 ±4.80m  
COGCC



location



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Caerus Piceance LLC  
B33NE  
Location # 335370

Mar 8, 2021 at 11:34:11 AM  
39.490282,-107.667497 ±4.81m  
COGCC



location

Mar 8, 2021 at 11:36:03 AM  
39.490302,-107.667110 ±4.80m  
COGCC



location



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



Caerus Piceance LLC  
B33NE  
Location # 335370



Debris



location entrance/ Evidence of lack of tracking controls





Caerus Piceance LLC  
B33NE  
Location # 335370



**Evidence of lack of tracking controls**



**Lack of stabilization/compaction**





**Caerus Piceance LLC**  
**B33NE**  
**Location # 335370**

Mar 8, 2021 at 11:35:10 AM  
39.490377,-107.667215 ±4.80m  
COGCC



Mar 8, 2021 at 11:34:54 AM  
39.490377,-107.667215 ±4.80m  
COGCC



**Lack of stabilization/compaction**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources