

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Domestic Tap /23SESW

Location ID: 458365



Photo #3090 Domestic tap from sales line.



Photo #3091 Big Joe regulator.

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Domestic Tap /23SESW

Location ID: 458365



**Photo #3092 Fluid knock out and little joe regulator.**



**Photo #3093 Isolation valve closed.**