

# *Inspection Photos*

*Loc#334739*

*Operator: Caerus*

*Insp#: 692403144*

*Insp Date: 3/3/21*



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



Photo#1:  
Overview of Location.

March 3, 2021



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Caerus GMR Loc#334739



Photo#2:  
Containers subject of CA Field Insp.



Photo#3:  
Pad perimeter

March 3, 2021



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Caerus GMR Loc#334739