

# Inspection Photos

API: 009-06450

Operator: INVESTMENT EQUIPMENT LLC

Inspection Date: 3/3/2021



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

API: 009-06450 | Date: 3/3/2021

## Inspection Photos



**Photo 1.** Facing southwest toward the battery facility.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 009-06450 | Date: 3/3/2021

## Inspection Photos



**Photo 2.** Facing southeast toward the well site.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 009-06450 | Date: 3/3/2021

## Inspection Photos



**Photo 3.** Facing toward the well. The pumpjack has been moved. It appears the well was plugged and abandoned on 11/19/2020.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 009-06450 | Date: 3/3/2021

## Inspection Photos



**Photo 4.** Facing southwest at the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 009-06450 | Date: 3/3/2021

## Inspection Photos



**Photo 5.** It appears a tank has been removed. All equipment and pipe risers need to be removed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 009-06450 | Date: 3/3/2021

## Inspection Photos



**Photo 6.** There is a tank and pumpjack at the south side of the location which needs to be removed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 009-06450 | Date: 3/3/2021

## Inspection Photos



**Photo 7.** Facing south toward the equipment at the west side of the location. The shed, tank, and all equipment will need to be removed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 009-06450 | Date: 3/3/2021

## Inspection Photos



**Photo 8.** Facing west at the north side of the location. Unused equipment stored at the location needs to be removed. The electric power pole and power line will also need to be removed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 009-06450 | Date: 3/3/2021

## Inspection Photos



**Photo 9.** Facing west at the location. All equipment needs to be removed. The location will need to be recontoured and reclaimed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 009-06450 | Date: 3/3/2021