

Inspection Photos

API: 009-06498

Operator: INVESTMENT EQUIPMENT LLC

Inspection Date: 3/3/2021



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 009-06498 | Date: 3/3/2021

Inspection Photos



Photo 1. Facing east toward the access road. The access road needs to be decompacted and reclaimed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06498 | Date: 3/3/2021

Inspection Photos



Photo 2. Facing northwest toward the location. All equipment has been removed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06498 | Date: 3/3/2021

Inspection Photos



Photo 3. This area at the location needs to be reclaimed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06498 | Date: 3/3/2021