




# Whiting Oil & Gas Corporation

## HORSETAIL 30F PAD CORRECTIVE ACTION INSPECTION PHOTOS

Location ID: 435694

Sec 30 T10N R57W

3-10-21



Horsetail 30F-1944 Wellhead Sign Installed



Horsetail 30F-3108 Wellhead Sign Installed