



# Whiting Oil & Gas Corporation

## HORSETAIL 30E PAD CORRECTIVE ACTION INSPECTION PHOTOS

Location ID: 445049

Sec 30 T10N R57W

1-25-21



Horsetail 30E-3135 Wellhead Sign Installed



Horsetail 30E-3104 Wellhead Sign Installed



# Whiting Oil & Gas Corporation

## HORSETAIL 30E PAD CORRECTIVE ACTION INSPECTION PHOTOS

Location ID: 445049

Sec 30 T10N R57W

3-10-21



Horsetail 30E-1903 Wellhead Sign Installed



Horsetail 30E-1904 Wellhead Sign Installed