

Inspection Photos

API: 071-06191

Operator: OGRIS OPERATING LLC

Inspection Date: 3/8/2021



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-06191 | Date: 3/8/2021

Inspection Photos



Photo 1. The cattle guard along the main road near the Bingham campground is filled in with sediment. The cattle guard needs to be cleaned out and maintained. Previous corrective action was not performed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06191 | Date: 3/8/2021

Inspection Photos



Photo 2. Stormwater is not properly diverted at the red arrow causing stormwater to pool in the vehicle ruts. This area needs to be repaired. (Lat/Long:37.071679,-104.91145) Previous corrective action was not performed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06191 | Date: 3/8/2021

Inspection Photos



Photo 3. The side of the road is filled in with sediment which is preventing stormwater from draining to the culvert.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06191 | Date: 3/8/2021

Inspection Photos



Photo 4. Sediment is accumulating along the main road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06191 | Date: 3/8/2021

Inspection Photos



Photo 5. Water from the river caused erosion across the access road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06191 | Date: 3/8/2021

Inspection Photos



Photo 6. Facing toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06191 | Date: 3/8/2021

Inspection Photos



Photo 7. There is opening where the still grate is around the wellhead. This area needs to be covered to prevent wildlife entry.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06191 | Date: 3/8/2021

Inspection Photos



Photo 8. There is oil and oily rags in the engine skid that need to be cleaned up.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06191 | Date: 3/8/2021

Inspection Photos



Photo 9. Sign posted on meter shed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06191 | Date: 3/8/2021

Inspection Photos



Photo 10. There is vehicle rutting west of the well where the drip line is located. Vehicle rutting and disturbance needs to be prevented with BMP's



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06191 | Date: 3/8/2021

Inspection Photos



Photo 11. Unsure of the purpose of the black poly line. If this does not serve a purpose it needs to be removed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06191 | Date: 3/8/2021