

Inspection Photos

3/9/2021

Operator: CAERUS PICEANCE LLC #10456

Location ID: 335574

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 335574



Photo 1: Photo taken from the east end of the Location, facing south. Photos 1-4 provide an overview of the Location from south, southwest, northwest to north.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Operator Name: CAERUS PICEANCE LLC #10456
Location ID: 335574



Photo 2: See comments under photo 1.



Inspection Photos
Operator Name: CAERUS PICEANCE LLC #10456
Location ID: 335574



Photo 3: See comments under photo 1.



Inspection Photos
Operator Name: CAERUS PICEANCE LLC #10456
Location ID: 335574



Photo 4: See comments under photo 1.



Location ID: 335574



Photo 5: Photo of Location sign at entrance.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC #10456
Location ID: 335574



Photo 6: Photo taken from the northern interim areas of the Location. Unclear as to when work was conducted, however recent reclamation activities evident; desirable vegetative establishment is evident. Location appears to be progressing towards reclamation standards.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC #10456
Location ID: 335574



Photo 7: Photo of the producing wells on the Location.



Inspection Photos
Operator Name: CAERUS PICEANCE LLC #10456
Location ID: 335574



Photo 8: Photo shows the ditch/berms along the pad and location's perimeter.

