

# Inspection Photos

3/9/2021

Operator: CAERUS PICEANCE LLC #10456

Location ID: 335978

Garfield County, CO

Aaron Trujillo  
NW Reclamation Specialist  
COGCC

Inspection Photos  
Operator Name: CAERUS PICEANCE LLC #10456  
Location ID: 335978



**Photo 1:** Photo taken from the north end of the Location, facing east. Photos 1-4 provide an overview of the Location from east, southeast, southwest to west.

Inspection Photos  
Operator Name: CAERUS PICEANCE LLC #10456  
Location ID: 335978



**Photo 2:** See comments under photo 1.

Inspection Photos  
Operator Name: CAERUS PICEANCE LLC #10456  
Location ID: 335978



**Photo 3:** See comments under photo 1.

Inspection Photos  
Operator Name: CAERUS PICEANCE LLC #10456  
Location ID: 335978



**Photo 4:** See comments under photo 1.

**Inspection Photos**  
**Operator Name: CAERUS PICEANCE LLC #10456**  
**Location ID: 335978**



**Photo 5:** Photo of Location sign at entrance.



Inspection Photos  
Operator Name: CAERUS PICEANCE LLC #10456  
Location ID: 335978



**Photo 6:** Photo of tank on the east end of the Location, and signage.

Inspection Photos  
Operator Name: CAERUS PICEANCE LLC #10456  
Location ID: 335978



**Photo 7:** Photo of the producing wells on the Location.

Inspection Photos  
Operator Name: CAERUS PICEANCE LLC #10456  
Location ID: 335978



**Photo 8:** Photo taken from the northern interim areas of the Location. Unclear as to when work was conducted, however recent reclamation activities evident; desirable vegetative establishment is evident. Location appears to be progressing towards reclamation standards.

Inspection Photos  
Operator Name: CAERUS PICEANCE LLC #10456  
Location ID: 335978



**Photo 9:** Photo taken from the southern interim areas of the Location. Unclear as to when work was conducted, however recent reclamation activities evident; desirable vegetative establishment is evident. Location appears to be progressing towards reclamation standards.