

# Inspection Photos

3/9/2021

Operator: CAERUS PICEANCE LLC #10456

Location ID: 335816

Garfield County, CO

Aaron Trujillo  
NW Reclamation Specialist  
COGCC

Inspection Photos  
Operator Name: CAERUS PICEANCE LLC #10456  
Location ID: 335816



**Photo 1:** Photo taken from the south end of the Location, facing west. Photos 1-4 provide an overview of the Location from west, northwest, northeast to east.

Inspection Photos  
Operator Name: CAERUS PICEANCE LLC #10456  
Location ID: 335816



**Photo 2:** See comments under photo 1.

Inspection Photos  
Operator Name: CAERUS PICEANCE LLC #10456  
Location ID: 335816



**Photo 3:** See comments under photo 1.

Inspection Photos  
Operator Name: CAERUS PICEANCE LLC #10456  
Location ID: 335816



**Photo 4:** See comments under photo 1.

Inspection Photos  
Operator Name: CAERUS PICEANCE LLC #10456  
Location ID: 335816



Photo 5: Photo of Location sign at entrance.

Inspection Photos  
Operator Name: CAERUS PICEANCE LLC #10456  
Location ID: 335816



**Photo 6:** Photo of tank on the northwest end of the Location, and signage.

Inspection Photos  
Operator Name: CAERUS PICEANCE LLC #10456  
Location ID: 335816



**Photo 7:** Photo taken from the northern interim areas of the Location, facing east. Unclear as to when work was conducted, however recent reclamation activities evident; desirable vegetative establishment is evident. Location appears to be progressing towards reclamation standards.