

Inspection Photos

3/9/2021

Operator: CAERUS PICEANCE LLC #10456

Location ID: 335804

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos
Operator Name: CAERUS PICEANCE LLC #10456
Location ID: 335804



Photo 1: Photo taken from the northeast end of the Location, facing south. Photos 1-3 provide an overview of the Location from south, southwest to west.



Inspection Photos
Operator Name: CAERUS PICEANCE LLC #10456
Location ID: 335804



Photo 2: See comments under photo 1.



Inspection Photos
Operator Name: CAERUS PICEANCE LLC #10456
Location ID: 335804



Photo 3: See comments under photo 1.



Inspection Photos
Operator Name: CAERUS PICEANCE LLC #10456
Location ID: 335804



Photo 4: Photo of signs at location entrance.



Inspection Photos
Operator Name: CAERUS PICEANCE LLC #10456
Location ID: 335804



Photo 5: Photo taken from the northern interim areas. Interim areas appear to be progressing towards COGCC 1003 Standards.



Inspection Photos
Operator Name: CAERUS PICEANCE LLC #10456
Location ID: 335804



Photo 6: Photo taken from the western interim areas. Interim areas appear to be progressing towards COGCC 1003 Standards. Photo also shows what appears to be monitoring wells. Remediation proj. #7742 currently in process.



Inspection Photos
Operator Name: CAERUS PICEANCE LLC #10456
Location ID: 335804



Photo 7: Photo of producing wells on the Location.

