

Inspection Photos

3/9/2021

Operator: CAERUS PICEANCE LLC #10456

Location ID: 335657

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos
Operator Name: CAERUS PICEANCE LLC #10456
Location ID: 335657



Photo 1: Photo taken from the south end of the Location, facing west. Photos 1-4 provide an overview of the Location from west, northwest, northeast to east.



Inspection Photos
Operator Name: CAERUS PICEANCE LLC #10456
Location ID: 335657



Photo 2: See comments under photo 1.



Inspection Photos
Operator Name: CAERUS PICEANCE LLC #10456
Location ID: 335657



Photo 3: See comments under photo 1.



Inspection Photos
Operator Name: CAERUS PICEANCE LLC #10456
Location ID: 335657



Photo 4: See comments under photo 1.



Inspection Photos
Operator Name: CAERUS PICEANCE LLC #10456
Location ID: 335657



Photo 5: Photo of signs at location entrance.



Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 335657



Photo 6: Photo taken from the northern interim areas. Interim areas appear to be progressing towards COGCC 1003 Standards.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 335657



Photo 7: Photo taken from the northeastern interim areas. Interim areas appear to be progressing towards COGCC 1003 Standards. Photo also shows stormwater run-on ditch and berm installed at interim areas.



Inspection Photos
Operator Name: CAERUS PICEANCE LLC #10456
Location ID: 335657



Photo 8: Photo taken from the wells. Photos 8-12 show unused equipment (risers) observed along the wells.



Inspection Photos
Operator Name: CAERUS PICEANCE LLC #10456
Location ID: 335657



Photo 9: See comments under photo 8.



Inspection Photos
Operator Name: CAERUS PICEANCE LLC #10456
Location ID: 335657



Photo 10: See comments under photo 8.



Inspection Photos
Operator Name: CAERUS PICEANCE LLC #10456
Location ID: 335657



Photo 11: See comments under photo 8.



Inspection Photos
Operator Name: CAERUS PICEANCE LLC #10456
Location ID: 335657



Photo 12: See comments under photo 8.

