

PHOTOGRAPHIC LOG

Project Name: 2020 RWSU On Site Spill Investigations	Site Location: FEE 19	Project No. 018-065
Description: Facing east. Salt/ alkaline crust present in low lying areas.		
Description: Facing south.		


PHOTOGRAPHIC LOG

Project Name: 2020 RWSU On Site Spill Investigations	Site Location: FEE 19	Project No. 018-065
Description: Facing north.		
Description: Facing northeast. Perimeter berm is well defined.		

PHOTOGRAPHIC LOG

Project Name: 2020 RWSU On Site Spill Investigations	Site Location: FEE 19	Project No. 018-065
Description: Spill path origin, south of the wellhead.		
Description: Facing low area of site surface north of the wellhead.		

PHOTOGRAPHIC LOG

Project Name: 2020 RWSU On Site Spill Investigations	Site Location: FEE 19	Project No. 018-065
Description: Facing south.		
Description: Facing southwest from the low point of the site.	