

# Inspection Photos

3/9/2021

Operator: CAERUS PICEANCE LLC #10456

Location ID: 335822

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

## Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 335822



**Photo 1:** Photo taken from the north end of the Location, facing northwest. Photo shows interim areas where control measures to stabilize the slopes and ditch are missing or insufficient. Photo also show reclamation in these areas are not progressing towards 1003 reclamation standards.





Inspection Photos  
Operator Name: CAERUS PICEANCE LLC #10456  
Location ID: 335822



**Photo 2:** See comments under photo 1.





Inspection Photos  
Operator Name: CAERUS PICEANCE LLC #10456  
Location ID: 335822



**Photo 3:** Photo taken from the interim areas on the north end of the Location. Photo shows that control measures to stabilize and protect the slopes are missing or insufficient. Uniform vegetative establishment on interim areas is not progressing towards 1003 standards.





Inspection Photos  
Operator Name: CAERUS PICEANCE LLC #10456  
Location ID: 335822



**Photo 4:** Photo taken from the interim areas on the north end of the Location, facing west. Photo shows that control measures to stabilize and protect the slopes are missing or insufficient. Uniform vegetative establishment on interim areas is not progressing towards 1003 standards.





Inspection Photos  
Operator Name: CAERUS PICEANCE LLC #10456  
Location ID: 335822



**Photo 5:** Photo taken from the stormwater ditch along the northern interim areas, facing west. Photo shows BMP is not in proper functioning condition; slopes along ditch have not been sufficiently stabilized; erosion degradation evident.





Inspection Photos  
Operator Name: CAERUS PICEANCE LLC #10456  
Location ID: 335822



**Photo 6:** Photo taken from the stormwater ditch along the northern interim areas, facing west. Photo shows BMP is not in proper functioning condition; slopes along ditch have not been sufficiently stabilized; erosion degradation evident.





Inspection Photos  
Operator Name: CAERUS PICEANCE LLC #10456  
Location ID: 335822



Photo 7: Photo shows sign at Location entrance.

