

Inspection Photos
Location Name: Rabbit Ears 0681 23
Location ID: 449274



Photo 1. Battery sign at entrance to location.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Location Name: Rabbit Ears 0681 23
Location ID: 449274



Photo 2. Tanks labeled with previous operator. No battery sign at battery.



Photo 3. Wellhead sign does not contain correct and necessary information.

