

Inspection Photos
Location Name: Surprise-Damfino S6 Pad
Location ID: 416625



Photo 1. Sign at entrance to location.



Inspection Photos
Location Name: Surprise-Damfino S6 Pad
Location ID: 416625



Photo 2. Wellhead sign does not contain correct and necessary information.



Photo 3. Wellhead sign does not contain correct and necessary information.



Inspection Photos
Location Name: Surprise-Damfino S6 Pad
Location ID: 416625



Photo 4. Battery sign and tank labels incomplete.



Photo 5. Battery sign and tank labels incomplete.

