

**Inspection Photos**  
**Location Name: Spicer Pad**  
**Location ID: 324754**



**Photo 1. Sign at entrance to location.**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

**Inspection Photos**  
**Location Name: Spicer Pad**  
**Location ID: 324754**



**Photo 2. Wellhead sign does not contain correct and necessary information.**



**Photo 3. Battery sign and tank labels incomplete.**

