

Inspection Photos
Location Name: DF Ranch 9-24, 32 Tank Battery
Location ID: 431338



Photo 1 – Tank Battery, South Tanks missing Capacity

Photo 2 – Tank Battery Signs

Inspection Photos
Location Name: DF Ranch 9-24, 32 Tank Battery
Location ID: 431338



Photo 3 – Missing Capacity Label



Photo 4 – Missing Capacity Label



Inspection Photos
Location Name: DF Ranch 9-24, 32 Tank Battery
Location ID: 431338



Photo 5 – Missing Capacity, Content and NFPA Label



Photo 6 – Missing Capacity, Content and NFPA Label

Inspection Photos
Location Name: DF Ranch 9-24, 32 Tank Battery
Location ID: 431338




Photo7 – Missing Capacity, Content and NFPA Label



Photo 8 – Heater Treaters, Gas Meters and ECD