

Construction and Stormwater Inspection

March 10, 2021

Operator: MAGPIE OPERATING, INC- #52530

Location ID: 307209

Inspection Document #: 697502648

Weld County, CO

NESW Section 29 T5N R68W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Bunker /8 Pad
Location ID: 307209



Photo 1. Photo taken from the entrance of location. Photo illustrates the Operator sign and the receptacle with the approved Form 2A.

Inspection Photos
Location Name: Bunker /8 Pad
Location ID: 307209



Photo 2. Photo taken from the northeastern perimeter of location, facing North. Photo illustrates there is no perimeter stormwater BMP in place during construction operations.

Inspection Photos
Location Name: Bunker /8 Pad
Location ID: 307209



Photo 3. Photo taken from the northeastern perimeter of location, facing West.
See comments under Photo 2.

Inspection Photos
Location Name: Bunker /8 Pad
Location ID: 307209



Photo 4. Photo taken from the northern perimeter of location on top of the topsoil stockpile, facing West. See comments under Photo 2.

Inspection Photos
Location Name: Bunker /8 Pad
Location ID: 307209



Photo 5. Photo taken from the western perimeter of location, facing South. See comments under Photo 2.