

**Inspection Photos**  
**Location Name: Troudt 18-27 Pad**  
**Location ID: 453618**



**Photo 1: Wellheads**



**Photo 2: Wellheads (in process of installing fencing)**

Inspection Photos  
Location Name: Troudt 18-27 Pad  
Location ID: 453618



Photo 3: No BBLs displayed on H2O tank



Photo 4: No BBLs displayed on crude oil tank.

Inspection Photos  
Location Name: Troudt 18-27 Pad  
Location ID: 453618



**Photo 5: No BBLs installed on H2O tank**