

Interim Reclamation Inspection

March 4, 2021

Operator: RENEGADE OIL & GAS COMPANY LLC - #74165

Location ID: 320706

Inspection Document #: 697502650

Arapahoe County, CO

SESW Section 15 T5S R64W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: STATE B #1
Location ID: 320706




Photo 1. Aerial imagery from 8/4/1969 illustrates there was not a pre-existing road going to the State B#1 well location. I marked the red diagonal line as the end point and the red circle as the approximate location of where the well was built.



Inspection Photos
Location Name: STATE B #1
Location ID: 320706



Photo 2. Aerial imagery from 9/29/199 illustrates the road that was constructed for the State B#1 well location.

Inspection Photos
Location Name: STATE B #1
Location ID: 320706



Photo 3. Photo taken from a drainage crossing along the access, facing South. SLB has requested to leave the road, as this is the only crossing point along the drainage.



Inspection Photos
Location Name: STATE B #1
Location ID: 320706



Photo 4. Photo taken from a portion of the lease road, facing South. Photo illustrates the lease road has not been reclaimed but the SLB has requested to leave it.

