

Caerus Piceance LLC
PG 11
Location # 334625

Mar 11, 2021 at 11:55:09 AM
39.454053,-107.962077 ±73.79m
COGCC



location

Mar 11, 2021 at 11:55:28 AM
39.454053,-107.962077 ±73.79m
COGCC




location



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Caerus Piceance LLC
PG 11
Location # 334625

Mar 11, 2021 at 11:55:07 AM
39.454053,-107.962077 ±73.79m
COGCC



location

Mar 11, 2021 at 11:55:47 AM
39.454036,-107.962222 ±4.69m
COGCC



location



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Caerus Piceance LLC
PG 11
Location # 334625

Mar 11, 2021 at 11:55:57 AM
39.454031,-107.962365 ±4.69m
COGCC



location

Mar 11, 2021 at 11:57:16 AM
39.453952,-107.962599 ±4.68m
COGCC




location



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Caerus Piceance LLC
PG 11
Location # 334625



Heavy Tracking onto county road from lease road is occurring. No tracking BMP are present at the time of inspection. Lack of stabilization/compaction



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Caerus Piceance LLC

PG 11

Location # 334625



Heavy Tracking onto county road from lease road is occurring. No tracking BMP are present at the time of inspection. Lack of stabilization/compaction



lack of stabilization/compaction



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources