

TEP  
PA 22-11  
Location #

Mar 11, 2021 at 12:16:49 PM  
39.454073,-107.962131 ±6.22m  
COGCC



location

Mar 11, 2021 at 12:17:11 PM  
39.451103,-107.956887 ±4.66m  
COGCC



location

TEP  
PA 22-11  
Location #



Location/ Tank battery signage at separators not at tank battery



Location around well heads still shows signs of lack of stabilization/compaction





TEP  
PA 22-11  
Location #

Mar 11, 2021 at 12:20:49 PM  
39.452903,-107.967052 ±4.67m  
COGCC



Mar 11, 2021 at 12:21:41 PM  
39.452887,-107.967451 ±4.65m  
COGCC



**Location around well heads still shows signs of lack of stabilization/compaction**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

TEP  
PA 22-11  
Location #

Mar 11, 2021 at 12:22:11 PM  
39.452887,-107.967451 ±4.65m  
COGCC



Mar 11, 2021 at 12:22:44 PM  
39.452883,-107.967083 ±4.67m  
COGCC



**Location around well heads still shows signs of lack of stabilization/compaction**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



TEP  
PA 22-11  
Location #

Mar 11, 2021 at 12:11:13 PM  
39.454073,-107.962131 ±6.22m  
COGCC



Mar 11, 2021 at 12:10:58 PM  
39.454067,-107.962116 ±6.68m  
COGCC



**Lease road shows signs of lack of stabilization/compaction**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



TEP  
PA 22-11  
Location #



**Heavy Tracking onto county road from lease road is occurring. No tracking BMP are present at the time of inspection. Lack of stabilization/compaction**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources