


Caerus Piceance LLC
PK 11
Location # 334733

Mar 11, 2021 at 1:34:19 PM
39.450797,-107.967922 ±107.30m
COGCC



location

Mar 11, 2021 at 1:35:39 PM
39.450793,-107.968180 ±4.68m
COGCC



location



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Caerus Piceance LLC
PK 11
Location # 334733

Mar 11, 2021 at 1:37:29 PM
39.450731,-107.967758 ±4.67m
COGCC



location

Mar 11, 2021 at 1:37:32 PM
39.450731,-107.967758 ±4.67m
COGCC



location



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Caerus Piceance LLC
PK 11
Location # 334733

Mar 11, 2021 at 1:38:13 PM
39.450707,-107.967619 ±4.67m
COGCC



location

Mar 11, 2021 at 1:37:05 PM
39.450819,-107.968060 ±4.68m
COGCC



Lack of stabilization/compaction on location



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Caerus Piceance LLC
PK 11
Location # 334733




Location entrance/lack of stabilization/compaction



Heavy Tracking onto county road from lease road is occurring. No tracking BMP are present at the time of inspection. Lack of stabilization/compaction.



Caerus Piceance LLC
PK 11
Location # 334733



Heavy Tracking onto county road from lease road is occurring. No tracking BMP are present at the time of inspection. Lack of stabilization/compaction.