

**Inspection Photos**  
**Location Name: DF Ranch 9-32**  
**Location ID: 414980**



**Photo 1 – Wellhead Sign**




**Photo 2 – Pumping Unit**



**Inspection Photos**  
**Location Name: DF Ranch 9-32**  
**Location ID: 414980**



**Photo 3 – Unused Downhole Equipment**



**Photo 4 – Unused Parts**





**Inspection Photos**  
**Location Name: DF Ranch 9-32**  
**Location ID: 414980**



**Photo 5 – Unmarked Risers**