

Inspection Photos
Location Name: DF Ranch PC GK 09-99HZ Tank Battery
Location ID: 448675



Photo 1 – Tank Battery



Photo 2 – Tank Battery Sign

Inspection Photos
Location Name: DF Ranch PC GK 09-99HZ Tank Battery
Location ID: 448675



Photo 3 – Missing Capacity Label, Weeds



Photo 4 – Weeds

Inspection Photos

Location Name: DF Ranch PC GK 09-99HZ Tank Battery

Location ID: 448675



Colorado Oil and Gas Conservation Commission
40.93592, -104.20366, 5212.3ft, 239°
03/08/2021 13:09:21

Photo 5 – Weeds