

Inspection Photos

Location Name: 70 RANCH USX BB /25-07P

Location #: 415365



Photo #1

70 Ranch USX BB 25-07P (05-123-31070) Wellsite

Temporarily Abandoned | TA

prior insp.



Photo #2

70 Ranch USX BB 25-07P Battery site

Abandoned

Unused Equipment: Gas meter run

prior insp.

Inspection Photos

Location Name: 70 RANCH USX BB /25-07P

Location #: 415365

Date & Time: Tue Mar 2 09:59:11 MST 2021
Position: +040.37334° / -104.37991°
Altitude: 1400m
Datum: WGS-84
Azimuth/Bearing: 174° S06E 3093mils (True)
Zoom: 1X
Chevron Response
To COGCC Inspection



Photo #3

70 Ranch USX BB 25-07P Battery site

Abandoned

Unused Equipment: *Gas meter run*

Now Removed

(Company provided photo)