

# *Inspection Photos*

*Loc#335453*

*Operator: Terra*

*Insp#: 692403183*

*Insp Date: 3/5/21*






Photo#1:  
View over Location.

March 5, 2021




**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Insp Photos: Terra Langstaff Loc#335453



Photo#2:  
BMP at West side of site.

March 5, 2021



Photo#3:  
Stormwater settling area.

Insp Photos: Terra Langstaff Loc#335453