

Inspection Photos

Loc#335742

Operator: Terra

Insp#: 692403186

Insp Date: 3/5/21



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:
Overview of Location.

March 5, 2021



Photo#2:
Site equipment.

March 5, 2021



Photo#3:
Pipeline/Flowline crossing site.