

# *Inspection Photos*

*Loc#335213*

*Operator: Terra*

*Insp#:692403190*

*Insp Date: 3/5/21*





Photo#1:  
Overviews of Location.

March 5, 2021



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Insp Photos: Terra Clough Loc#335213



Photo#2:  
Interim area.

March 5, 2021



Photo#3:  
Anchor run over and buried in pad surface.